INDOOR > MULTI-OPTIC RECESSED SPOTS > MATRIX





LAMPADA - BULB PREVALED COIN 111



Codice Code	Watt	Volt	Fascio Beam	Lumen	Kelvin
646338-930	26W	700mA	15°	2350	3000K
646338-940	26W	700mA	15°	2500	4000K
646339-930	26W	700mA	24°	2250	3000K
646339-940	26W	700mA	24°	2400	4000K
646340-930	26W	700mA	40°	2150	3000K
646340-940	26W	700mA	40°	2300	4000K
646347-930	37W	1050mA	24°	2450	3000K
646347-940	37W	1050mA	24°	3800	4000K
646348-930	37W	1050mA	40°	3350	3000K
646348-940	37W	1050mA	40°	3550	4000K



Gli apparecchi non sono muniti nè di lampada nè di driver che potranno essere ordinati a SIDE a seconda del tipo di fascio e di potenza desiderata. The fixtures are not equipped with lamp or a power supply which can be ordered from SIDE according to the type of beam and desired power.

FEATURES

Intended Use:	Interior	
Installation:	Recessed Ceiling	
Recessed hole:	ø 196x196 mm	
Fixing:	With brackets provided	
Body/Structure:	Sheet steel body	
Painting:	Interior polyester powder coating	
Finish:	White	
Driver:	Not included; must be ordered separately	

TECHNICAL DATA

Insulation class:	3	
Weight:	3.8 kg	
IP grade:	20	
Glow wire:	650 °C	
Nominal duration:	50.000 (h) L80 B20	















attached photometry referring to lamp 12v 50w 24° possibility to install led111 lamp with appropriate ballast


MATRIX 111 - 4 LED

70411



INDOOR > MULTI-OPTIC RECESSED SPOTS > MATRIX

TECHNICAL DRAWING



COMPANY

Side Spa has always been a benchmark in the manufacturing industry for its constant focus on product quality, assembly and sustainability of its items. The company is distinguished by its dedication to offering customers the highest quality products that meet needs and exceed expectations.

Side Spa pays the utmost attention to the quality of its products. Each stage of production undergoes rigorous quality control to ensure that only first-class items reach the market. By using high-quality materials and adopting state-of-the-art manufacturing processes, the company is able to offer products that stand the test of time and maintain their performance over the years. Quality is a top priority for Side Spa, which strives to meet the highest standards of excellence.

